





ENGINEERING BETTER BEER

eBrewing Kit Product Guide

HOT SIDE



STRIKE / SPARGE




KEY

- STRIKE/SPARGE TUBING
- WHIRLPOOL TUBING
- RUN-OFF TUBING

NOTE

- USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS -

WHIRLPOOL




NOTE

 - USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS - 

COLD SIDE / TRANSFER

WITH IMMERSION WORT CHILLER




NOTE

- USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS -

COLD SIDE / TRANSFER

WITH INLINE HEAT EXCHANGER



NOTE




- USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS -



COLD SIDE / TRANSFER

WITH FERMENTER LID MOUNTED IMMERSION CHILLER COIL

CHRONICAL BME
OR UNITANK



NOTE

- USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS -