



ENGINEERING BETTER BEER

3V eBrewing Kit Product Guide

QUICK START GUIDES

QUICK START
GUIDES
FAQs
SUPPORT



TAKE A
PHOTO
OF THE QR
CODE


www.SsBrewtech.com/guides

This Guide is for set up and basic use of your 3V eBrewing system. For details on the eKettles, eController, InfuSsion Mash Tun and RIMS, please check out our individual guides for those in our Quick Start Guide page on our website.


SsBREWTECH.COM

PUMP FITTINGS


CHUGGER NPT PUMP




CHUGGER TC PUMP




RECOMMENDED eBREWING 3V SETUP



HOT SIDE



STRIKE / SPARGE / RIMS




KEY

- STRIKE/SPARGE TUBING
- WHIRLPOOL TUBING
- RUN-OFF TUBING
- RIMS TUBING

NOTE

- USE HOSE CLAMPS ON ALL BARB FITTINGS
- USE TEFLON TAPE ON ALL THREADED FITTINGS -

WHIRLPOOL




NOTE

 - USE HOSE CLAMPS ON ALL BARB FITTINGS
 USE TEFLON TAPE ON ALL THREADED FITTINGS -

COLD SIDE / TRANSFER

WITH IMMERSION WORT CHILLER




NOTE

- USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS -

COLD SIDE / TRANSFER


WITH INLINE HEAT EXCHANGER



COLD SIDE / TRANSFER

WITH FERMENTER LID MOUNTED IMMERSION CHILLER COIL

CHRONICAL BME
OR UNITANK



NOTE

USE HOSE CLAMPS ON ALL BARB FITTINGS
USE TEFLON TAPE ON ALL THREADED FITTINGS